BOR-BUILDING INVENTORY EDIT FALL DATA 2017 RUN DATE 11/13/2017 14:42:47 PAGE NUMBER 1 L.E. FLETCHER TECHNICAL COMM. COLL. BRANCH PARISH

RELATION OTHER

ERRORS/WARNINGS	NO.	B U I L D NAME	I N G STATUS & STATE ID		AREAS GROSS				-REPLACE V/BLDG. (000)	NO. OF FLOORS
	LAMA	331 Dickson Rd-LAM	OWNED BY INST. SATISFACTORY S04468	15,871	21,034	1980		1,106	1,786	2
	LAMB	331 Dickson Rd-LAM	OWNED BY INST. SATISFACTORY S04469	4,033	5,210	1980		2,347	380	1
	LAMC	331 Dickson Rd-Tra	OWNED BY INST. SATISFACTORY S28707	13,742	21,635	2014		5,317	5,317	2
	LEFA	310 St. Charles St	OWNED BY INST. SATISFACTORY S04466	54,221	89,982	1951	1977	9,592	6,712	2
	LEFB	310 St. Charles St	OWNED BY INST. SATISFACTORY S04467	2,762	2,763	1975		12	28	1
	LEFC	310 St. Charles St	OWNED BY INST. SATISFACTORY S13589	736	737	2003		33	33	1
	LEFD	310 St. Charles St	OWNED BY INST. SATISFACTORY S15256	1,472	1,473	2006		33	33	1
	SCH1	1407 Hwy 311-Main	OWNED BY INST. SATISFACTORY L28073	59,707	99,420	2012	:	21,120	21,120	2
	SCH2	224 Weatherford Dr	OWNED BY INST. SATISFACTORY S23009	14,320	25,475	2014		5,523	5,523	2

BOR-BUILDING INVENTORY EDIT FALL DATA 2017 RUN DATE 11/13/2017 14:42:47 PAGE NUMBER 2 L.E. FLETCHER TECHNICAL COMM. COLL.
BRANCH
PARISH
RELATION OTHER

DESCRIPTION AND SUMMARY OF ERRORS & WARNINGS	
A = ERROR - DUPLICATE BLDG B = ERROR - DUPLICATE SUPPLEMENT	
E = ERROR - INVALID OWNERSHIP STATUS CODE	
P = ERROR - GROSS AREA = ZEROS OR BLANK	
Q = WARNING - CONSTRUCTION DATE PRIOR TO 1800 OR BLANK	
T = WARNING - NET ASSIGNABLE SQ FT, CUSTODIAL, CIRCULATION AND MECHANICAL ARE ALL ZEROS OR BLANK (NO ROOMS ASSIGNED TO THIS BUILDING OR BUILDING CONTAINS ONLY ROOMS WITH TYPES OF 010, 020 OR 030)	
U = WARNING - NET ASSIGNABLE SQ FT = ZEROS OR BLANK WITH CUSTODIAL, CIRCULATION OR MECHANICAL > ZERO	
TOTALS	
TOTAL NUMBER OF BLDGS (MATCHED)	
TOTAL ERRORS	
TOTAL WARNINGS	
TOTAL BOOK VALUE OF BLDGS (IN THOUSANDS) TOTAL EST VALUE OF BLDGS (IN THOUSANDS)	45 40
TOTAL GROSS AREA OWNED BY INST. TOTAL GROSS AREA LEASED BY INST	267
TOTAL GROSS AREA	267

^{**} PLEASE REFER TO THE FACILITIES MANUAL TO OBTAIN THE CORRECT CODES.